

### 46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT



#### Kia Sportage 1.6 GDi ISG 2 5dr Inspection Vehicle nama Serious Damage? VAT No Margin ٧5 Present Details 2 £3,375.00 Reg. date 21/10/2015 Keys CAP Clean £2,875.00 Year 2015 Service history Yes CAP Average 94,333 Miles Service Book CAP Below £2,375.00 Mileage Service documents Warranted Gearbox MANUAL Number of stamps 6 Fuel Type Petrol 17/12/2020 Gears Last service date 6 SILVER Colour Last service miles 47,306 VIN U5YPC814LFL741409 MOT Due 15/12/2025 **Body Style** Estate

### £100 ADDITIONAL FEE LAST SERVICE 17/12/20 @ 47306 MILES (6 MAIN DEALER) BOOK Oil light is on

Tyres			
NSF	BUDGET	3.0mm	
NSR	BUDGET	5.0mm	
OSF	BUDGET	3.0mm	
OSR	BUDGET	5.0mm	
Spare			

## Features

- Bluetooth connection
- Telephone
- · Electric sunroof
- · Front electric windows
- ABS
- Tyre pressure monitor Leather seat trim
- Air conditioning Rear electric windows Drivers airbag
- Central locking

Cruise control Radio/CD

Alloy wheels

- •
- Rear parking sensor Body coloured bumpers Climate control •
- ٠
- Rear headrests •
- Passenger airbag Remote central locking
- Metallic Paint Traction control

.

· Rear wiper

Cloth seat trim

Front armrest

Electric door mirrors

**Photos** 






















# **Condition Check**




### **Damage Photos**



1: Wheel osf Scratched Over 50mm

2: Wing osf Chipped 1 To 5




3: Door osf Chipped 1 To 5



5: Wheel osr Corroded Light



4: Door osr Poor Previous Repair Poor Paint



6: Bumper Rear Moulding Broken Replace



7: Wheel nsr Corroded Light




8: Door nsr Scratched Over 25mm Not Thru Paint





9: Door nsf Chipped Edge Chip



11: Wheel nsf Corroded Light

### Interior

Carpet Condition Seat Condition Average Average Upholstery Condition Odour

Broken

Replace

Average No

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

10: Door nsf Chipped 1 To 5



EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK