



# VEHICLE INSPECTION REPORT

**FV09KLO**

## Toyota Yaris 1.4 D-4D TR 5dr [6]

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

### Details

Reg. date 28/06/2009

Year 2009

Mileage 124,276 Miles  
Warranted

Fuel Type Diesel

Colour SILVER

VIN VNKKC96310A215801

Body Style Hatchback

Keys 1

Service history Yes

Service documents Printout

Number of stamps 2

Last service date 06/06/2022

Last service miles 95,479

MOT Due 29/06/2025

CAP Clean £910.00

CAP Average £520.00

CAP Below £225.00

Gearbox MANUAL

Gears 6

Doors 5

Last Service: 06/06/2022 at 95479 miles. (2 services )

### Tyres

NSF RAPID 4.0mm

NSR CONSTANCY 5.0mm

OSF RAPID 2.0mm


OSR CONSTANCY 5.0mm

Spare

## Features


- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Steel wheels
- Electric door mirrors
- Metallic Paint
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Dented  
2 Or Less UpTo 10mm



2: Qtr Panel osr  
Dented  
Between 10mm + 30mm





3: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



4: Bumper Rear  
Chipped  
Multiple Chips



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Bumper Front  
Scratched  
Over 100mm Thru Paint



8: Roof  
Dented  
Over 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK