



VEHICLE INSPECTION REPORT

GY14DOH

Nissan Juke 1.6 N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/04/2014	Keys	2	CAP Average	£2,275.00
Year	2014	Service history	Yes	CAP Below	£1,800.00
Mileage	86,264 Miles Warranted	Number of stamps	5	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	08/06/2025	Gears	5
Colour	BLACK	Last service miles	78,387	Doors	5
VIN	SJNFBAF15U6518382	MOT Due	27/04/2026		
Body Style	Hatchback	CAP Clean	£2,775.00		

Last Service: 08/04/2024 at 78387 miles. (5 services)

Tyres


NSF	TRIANGLE	5.0mm
NSR	BUDGET	5.0mm
OSF	TRIANGLE	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Park assist camera
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wheel osr
Corroded
Light




3: Wheel nsr
Corroded
Light



4: Wheel nsf
Corroded
Light



5: Wing osf
Chipped
1 To 5



6: Door osf
Chipped
Edge Chip



7: Door osr
Chipped
Edge Chip



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Poor Previous Repair
Paint Flake



10: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



11: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



12: Door nsr
Scratched
UpTo 25mm Thru Paint



13: Door nsf
Dented
Over 30mm



14: Wing nsf
Chipped
1 To 5



15: Bumper Front
Poor Previous Repair
Paint Flake



16: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK