



VEHICLE INSPECTION REPORT

LS72SY

Toyota Aygo X 1.0 VVT-i Edge 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	14/10/2022	Body Style	Hatchback	Last service miles	63,775
Year	2022	Keys	2	Gearbox	MANUAL
Mileage	69,187 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	GREEN	Number of stamps	5		
VIN	JTDAGNAC500060670	Last service date	14/02/2025		

Ex-driving school vehicle. Last Service: 14/02/2025 at 63775 miles. (5 main dealer services) Dual pedals in vehicle but not connected

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	6.0mm
OSF	CONTINENTAL	4.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Dented
Between 10mm + 30mm




2: Wheel osr
Scratched
Over 50mm



3: Wheel nsf
Scratched
Over 50mm



4: Bonnet
Dented
Over 30mm



5: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK