

VEHICLE INSPECTION REPORT



Kia Venga 1.6 4 5dr Auto [6]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	Present		
Details					
Reg. date	01/03/2018	Keys	2	CAP Clean	£8,075.00
Year	2018	Service history	Yes	CAP Average	£7,100.00
Mileage	42,564 Miles Warranted	Service documents	Service Book	CAP Below	£6,100.00
		Number of stamps	6	Gearbox	AUTOMATIC
Fuel Type	Petrol	Last service date	05/06/2024	Gears	6
Colour	RED	Last service miles	35,284	Doors	5
VIN	U5YEH812MJL187771	MOT Due	28/02/2026		-
Body Style	Hatchback		20, 02, 2020		

Last Service: 05/06/2024 at 35284 miles. (6 main dealer services)

Tyres			
NSF	GT RADIAL	6.0mm	
NSR	FALKEN	5.0mm	
OSF	GT RADIAL	5.0mm	
OSR	BUDGET	4.0mm	
Spare			

Features

- · Heated front seat
- Rear wiper
 Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system Telephone Electric sunroof . •

٠

- Front electric windows •
- ABS ٠
- Tyre pressure monitor
- Leather seat trim
- Park assist cameraRadio/CD
- - Air conditioning Rear electric windows •
 - •
 - Drivers airbag •
 - Central locking •
 - Alloy wheels
- Rear parking sensor
 Body coloured bumpers
 Climate control
- Rear headrests
- Passenger airbagRemote central locking

Photos






















Condition Check




Damage Photos



1: Wheel os Corroded Light

2: Wheel osi Corroded Light







4: Wheel nsr Corroded Light



5: Wheel nsf Corroded Light

Interior

Carpet Condition Seat Condition Average Average Upholstery Condition Odour Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK



6: Bonnet Chipped 1 To 5

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	ОК
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		