



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GK19YCR

Citroen C5 Aircross BLUEHDI C-SERIES EDITION S/S

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2019	Body Style	Hatchback	Last service miles	83,117
Year	2019	Keys	2	MOT Due	03/09/2025
Mileage	85,139 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	8	Doors	5
VIN	VR7ACYHZJKL023820	Last service date	17/03/2025		

Last Service: 17/03/2025 at 83117 miles. (8 services (6 main dealer()

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Corroded
Light



4: Wheel nsr
Corroded
Light



5: Door nsr
Chipped
1 To 5



6: Bumper Front
Scratched
Over 25mm Not Thru Paint



7: Bonnet
Chipped
1 To 5




8: Door nsf
Dented
2 Or Less UpTo 10mm




9: Door nsf
Chipped
1 To 5



10: Wing nsf
Chipped
1 To 5



11: Door osr
Chipped
1 To 5



12: Door osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		