



VEHICLE INSPECTION REPORT

OV13GHH

Land Rover Range Rover Evoque 2.2 SD4 Dynamic 3dr Auto [Lux Pack]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/05/2013	Keys	2	CAP Clean	£5,800.00
Year	2013	Service history	Yes	CAP Average	£5,025.00
Mileage	79,667 Miles Warranted	Service documents	Service Book	CAP Below	£4,250.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	24/03/2025	Gears	6
VIN	SALVA1AE6DH794554	Last service miles	78,024		
Body Style	Coupe	MOT Due	30/03/2026		

Last Service: 24/03/2025 at 78024 miles. (6 services (1 main dealer)). Book & print.

Tyres

NSF	PIRELLI	Damaged
NSR	PIRELLI	3.0mm
OSF	BRIDGESTONE	4.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Tailgate
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bonnet
Poor Previous Repair
Poor Paint

No Image

10: Tyre nsf
Damaged
Replace



11: Other
N/A
N/A

No Image

12: Tyre nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK