



# VEHICLE INSPECTION REPORT

**OV55HHB**

## Vauxhall Movano 3500 MWB H/R P/V CDTI

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/09/2005	Colour	WHITE	Gearbox	MANUAL
Year	2005	VIN	VN1F9CVH533263435	Gears	5
Mileage	89,355 Miles Warranted	Body Style	Panel Van	Doors	5
Fuel Type	Diesel	MOT Due	29/09/2025		

Intermittent clutch pedal sticking down  
Bonnet release broken and handbrake bearily holds


### Tyres

NSF	AVON	4.0mm
NSR	BUDGET	3.0mm
OSF	GOODRIDE	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Radio/CD
- Drivers airbag
- Central locking
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Seat Base Cover osf  
Torn  
Over 3mm





3: Seat Back Cover osf  
Torn  
Over 3mm



4: Bonnet  
Chipped  
Multiple Chips



5: Bumper Front  
Chipped  
Multiple Chips



6: Wing nsf  
Poor Previous Repair  
Poor Paint



7: Door nsf  
Dented  
With Paint Damage



8: Door nsr  
Dented  
Over 30mm



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Boot Lid  
Dented  
With Paint Damage



11: Qtr Panel osr  
Dented  
Over 30mm



12: Door osf  
Poor Previous Repair  
Poor Paint



13: Wing osf  
Poor Previous Repair  
Poor Paint



14: Screen Front  
Chipped  
Over 10mm



15: Roof  
Chipped  
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK