



VEHICLE INSPECTION REPORT

YC58YHL

Mini Hatchback 1.6 Cooper D 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	26/11/2008	Body Style	Hatchback	Last service miles	87,947
Year	2008	Keys	2	MOT Due	04/06/2026
Mileage	94,574 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	9	Doors	3
VIN	WMWVG32050TV26714	Last service date	02/10/2023		

Last Service: 02/10/2023 at 87947 miles. (9 services (5 main dealer)) HIGH CLUTCH

Tyres

NSF	YOKOHAMA	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	YOKOHAMA	5.0mm
OSR	YOKOHAMA	4.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Metallic Paint
- Tyre pressure monitor
- Leather seat trim
- Telephone
- Air conditioning
- ABS
- Central locking
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



2: Door osf
Chipped
Edge Chip



3: Door osf
Chipped
1 To 5



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Chipped
1 To 5




6: Wheel osf
Scratched
Over 50mm



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Bumper Rear
Hole
UpTo 25mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Door nsf
Chipped
Edge Chip



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bonnet
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK