



VEHICLE INSPECTION REPORT

RE17ZNP

Dacia Sandero 1.0 SCe Ambiance 5dr

Cat: S
Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 07/06/2017

Year 2017

Mileage 84,284 Miles
Warranted

Fuel Type Petrol

Colour WHITE

VIN UU15SDMC557919474

Body Style Hatchback

Keys 1

Service history Yes

Service documents Printout

Number of stamps 2

Last service date 19/02/2025

Last service miles 72,224

MOT Due 18/02/2026

CAP Clean £2,150.00

CAP Average £1,700.00

CAP Below £1,250.00

Gearbox MANUAL

Gears 5

Doors 5

£65 ADDITIONAL FEE. LAST SERVICE 19/2/25 @ 72224 MILES (2 SERVICES) PRINT

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair. EML LIGHT ON

Tyres

NSF

NSR SAILUN 3.0mm

OSF BUDGET 5.0mm

OSR KUMHO 2.0mm

Spare

Features


- Rear wiper
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Rear headrests
- Passenger airbag
- Steel wheels
- Body coloured bumpers
- Solid Paint
- Central locking
- Air conditioning
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint



3: Bumper Rear
Scratched
Up To 25mm Thru Paint



4: Bumper Rear
Chipped
Multiple Chips



5: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



6: Qtr Panel nsr
Chipped
1 To 5



7: Wing nsf
Poor Previous Repair
Poor Paint



8: Bumper Front
Cracked
Over 25mm



9: Bonnet
Poor Previous Repair
Poor Paint



10: Screen Front
Chipped
UpTo 10mm



11: Seat Base Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK