



VEHICLE INSPECTION REPORT

LF63SZY

Daf Trucks LF FA 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

nama
GRADE
4

Details

Reg. date 02/10/2013

Year 2013

Mileage 398,241 Miles
Warranted

Fuel Type Diesel

Colour BLUE

VIN XLRAE45FF0L427273

Body Style Box Van

Keys 2

Service history Yes

Service documents Printout

Number of stamps 13

Last service date 08/11/2024

MOT Due 30/09/2025

Cab Type Day

Gearbox Manual

Gears 5

Axle Combi 4x2

Tail Lift Tuckaway

Last Service: 08/11/2024 at 608600 KM = 378166 miles. (13 services) Starting fault

Tyres

NSF 7.0mm

NSI1

NSI2

7.0mm

NSI3

NSI4

OSF 4.0mm

OSI1

OSI2

6.0mm

OSI3

OSI4

Spare

NSO1

NSO2

7.0mm

NSO3

NSO4

OSO1

OSO2

6.0mm

OSO3

OSO4

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door osf
Chipped
1 To 5

No Image



3: Door osf
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel osr
Dented
With Paint Damage



5: Boot Lid
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK