



VEHICLE INSPECTION REPORT

GY63VNM

Ford Fiesta 1.25 Style 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/01/2014	Keys	2	CAP Clean	£2,050.00
Year	2014	Service history	Yes	CAP Average	£1,600.00
Mileage	79,764 Miles Warranted	Service documents	Service Book	CAP Below	£1,175.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	BLUE	Last service date	16/04/2021	Gears	5
VIN	WF0CXXGAKCEL83432	Last service miles	50,161	Doors	3
Body Style	Hatchback	MOT Due	31/01/2026		

£100 ADDITIONAL FEE. LAST SERVICE 16/4/21 @ 50161 MILES (7 SERVICE 6 MAIN DEALER) BOOK


Tyres

NSF	BUDGET	5.0mm
NSR	PIRELLI	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Electric door mirrors
- Metallic Paint
- Traction control
- Steel wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Dented
Between 10mm + 30mm



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Dented
With Paint Damage



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Qtr Panel nsr
Chipped
1 To 5



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door Mirror Assy nsf
Broken
Replace



10: Wing nsf
Scratched
Over 25mm Not Thru Paint



11: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK