



## VEHICLE INSPECTION REPORT

**NA14TGU**

### Skoda Yeti Outdoor 2.0 TDI CR [140] Laurin + Klement 4x4 5dr DSG

#### Inspection

Serious Damage? No

#### Vehicle

VAT Margin

V5 TBC

nama  
GRADE  
2

#### Details

Reg. date	28/05/2014	VIN	TMBMD75L6E6044381	CAP Average	£9,100.00
Year	2014	Body Style	Hatchback	CAP Below	£8,000.00
Mileage	33,712 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Diesel	MOT Due	01/09/2025	Gears	6
Colour	BEIGE	CAP Clean	£10,200.00	Doors	5

£100 ADDITIONAL FEE.


#### Tyres


NSF	TIGAR	5.0mm
NSR	TIGAR	6.0mm
OSF	TIGAR	5.0mm
OSR	TIGAR	6.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Towbar
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
1 To 5






3: Door osf  
Chipped  
Edge Chip



4: Wheel osr  
Scratched  
Over 50mm



5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Bumper Rear  
Chipped  
Multiple Chips



7: Wheel nsr  
Scratched  
Up To 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		