

## **VEHICLE INSPECTION REPORT**

ez-Go

# **Ez-go Golf Buggy Full Waterproofs**

| Inspection         |             | Vehicle |           |       |   | nama  |
|--------------------|-------------|---------|-----------|-------|---|-------|
| Serious Damage? No |             | VAT     | Margin    |       |   | GRADE |
|                    |             | V5      | TBC       |       |   |       |
| Details            |             |         |           |       |   |       |
| Reg. date          |             | Colour  | GREEN     | Gears | 1 |       |
| Year               |             | VIN     |           | Doors | 2 |       |
| Mileage            | TBC         | Keys    | 1         |       |   |       |
| Fuel Type          | ELECTRICITY | Gearbox | AUTOMATIC |       |   |       |
|                    |             |         |           |       |   |       |

Direct from High Court Enforcement . Complete with rain covers .

| Tyres |        |       |  |
|-------|--------|-------|--|
| NSF   | BUDGET | 3.0mm |  |
| NSR   | BUDGET | 3.0mm |  |
| OSF   | BUDGET | 3.0mm |  |
| OSR   | BUDGET | 3.0mm |  |
| Spare |        |       |  |













## **Condition Check**



## **Damage Photos**



1: Bumper Front Chipped Multiple Chips No Image

2: Bumper Front Scratched Over 25mm Not Thru Paint



3: Qtr Panel osr Scratched Over 25mm Thru Paint



4: Qtr Panel nsr Scratched Over 25mm Thru Paint

#### Interior

Carpet Condition - Upholstery Condition - Seat Condition - Odour -

## **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
|--------------------------|----|--|----|
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
|                          |    | , , , , , , , , , , , , , , , , , , ,          |    |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |  |    |
| Windows                  | OK | Radio  | OK |
|                          |    | Steering                                       | OK |