



VEHICLE INSPECTION REPORT

BG06ENV

Nissan Micra 1.4 SVE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/04/2006	Keys	2	CAP Clean	£1,125.00
Year	2006	Service history	Yes	CAP Average	£740.00
Mileage	72,165 Miles Warranted	Service documents	Service Book	CAP Below	£350.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	AUTOMATIC
Colour	GREY	Last service date	08/01/2021	Gears	4
VIN	SJNFCAK12U2120731	Last service miles	54,797	Doors	5
Body Style	Hatchback	MOT Due	28/06/2025		

LAST SERVICE 8/1/21 @ 54797 MILES (10 SERVICE 7 MAIN DEALER) BOOK AND PRINT Slight noise from engine

Damage behind rear bumper

Tyres



NSF	BUDGET	Illegal
NSR	DUNLOP	Illegal
OSF	ROADSTONE	2.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Rear parking sensor
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Metallic Paint
- Central locking
- Radio/CD
- Climate control
- ABS
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
2 Or Less UpTo 10mm



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Dented
Over 30% Of Panel



8: Tailgate
Dented
Over 30% Of Panel



9: Other
N/A
N/A



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
Over 30mm



13: Door nsf
Chipped
1 To 5



14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Poor Previous Repair
Poor Paint



16: Bonnet
Dented
Over 30mm



17: Bumper Front
Poor Previous Repair
Paint Flake



18: Door Pad nsf
Scuffed
Over 25mm



19: Sill ns
Rusted
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK