

VEHICLE INSPECTION REPORT

LY09HCE

Vauxhall Agila 1.2 16V Club 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/07/2009	Keys	2	CAP Clean	£830.00
Year	2009	Service history	Yes	CAP Average	£430.00
Mileage	59,938 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	SILVER	Last service date	08/07/2019	Gears	5
VIN	W0LFXB32S9M257228	Last service miles	45,187	Doors	5
Body Style	Hatchback	MOT Due	09/11/2025		

LAST SERVICE 8/7/19 @ 45187 MILES (7 SERVICE 5 MAIN DEALER) BOOK Clutch is stiff

Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Steel wheels
- Electric door mirrors
- Metallic Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Wing osf
Dented
2 Or Less UpTo 10mm



3: Door osf
Dented
2 Or Less UpTo 10mm



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Bumper Rear
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



7: Door nsr
Chipped
1 To 5



8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Door nsf
Scratched
UpTo 25mm Thru Paint



10: Bumper Front
Scratched
UpTo 25mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: A Post os
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK