



VEHICLE INSPECTION REPORT

KU09ONG

Volkswagen Golf 1.4 TSI 160 GT 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	13/03/2009	Keys	2	CAP Clean	£2,300.00
Year	2009	Service history	Yes	CAP Average	£1,850.00
Mileage	98,380 Miles Warranted	Service documents	Service Book	CAP Below	£1,400.00
Fuel Type	Petrol	Number of stamps	13	Gearbox	SEMI AUTO
Colour	WHITE	Last service date	22/06/2022	Gears	7
VIN	WVWZZZ1KZ9W472947	Last service miles	60,791	Doors	5
Body Style	Hatchback	MOT Due	20/09/2025		

£65 ADDITIONAL FEE. LAST SERVICE 22/6/22 @ 60791 MILES (13 SERVICES 9 MAIN DEALER) BOOKS
Roof lining dropped

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Wheel osr
Scratched
Over 50mm



5: Bumper Rear
Poor Previous Repair
Poor Paint



6: Wheel nsr
Scratched
Over 50mm



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Chipped
1 To 5



9: Bumper Front
 Scratched
 Over 100mm Thru Paint



10: Bonnet
 Chipped
 Multiple Chips



11: Roof
 Chipped
 1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK