

VEHICLE INSPECTION REPORT

GP66GHU

Volkswagen Golf 2.0 TDI GTD 5dr DSG [Nav]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	16/11/2016	VIN	WVWZZZAUZHW097066	CAP Average	£10,250.00
Year	2016	Body Style	Hatchback	CAP Below	£9,175.00
Mileage	52,852 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Diesel	MOT Due	15/11/2025	Gears	6
Colour	GREY	CAP Clean	£11,350.00	Doors	5

£65 ADDITIONAL FEE.


Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Wheel nsr
Scratched
Over 50mm



4: Wheel nsf
Scratched
Over 50mm




5: Other
N/A
N/A



6: Door osf
Chipped
1 To 5



7: Door nsr
Dented
2 Or Less UpTo 10mm



8: Door nsr
Chipped
1 To 5



9: Bumper Front
 Scratched
 25 to 100mm Thru Paint



10: Bonnet
 Scratched
 UpTo 25mm Thru Paint



11: Screen Front
 Chipped
 UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK