



VEHICLE INSPECTION REPORT

GU15FWL

Volkswagen Polo 1.0 75 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	01/03/2015	VIN	WVWZZZ6RZFU022684	CAP Average	£4,575.00
Year	2015	Body Style	Hatchback	CAP Below	£3,900.00
Mileage	61,021 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	17/02/2026	Gears	5
Colour	WHITE	CAP Clean	£5,300.00	Doors	5

£65 ADDITIONAL FEE.


Tyres

NSF	KUMHO	4.0mm
NSR	LAUFENN	4.0mm
OSF	HANKOOK	4.0mm
OSR	RAPID	4.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Chipped
Multiple Chips

No Image

10: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Wheel osr
Scratched
Over 50mm




13: Door osr
Chipped
1 To 5

No Image


14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK