



VEHICLE INSPECTION REPORT

DE08AAY

Honda Accord 2.0 i-VTEC EX 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	28/03/2008	Colour	BLACK	MOT Due	20/10/2025
Year	2008	VIN	JHMCL76908C211195	Gearbox	AUTOMATIC
Mileage	51,196 Miles Warranted	Body Style	Saloon	Gears	5
Fuel Type	Petrol	Keys	2	Doors	4

Tyres

NSF	PIRELLI	5.0mm
NSR	GOODYEAR	6.0mm
OSF	PIRELLI	6.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Central locking
- Heated front seat
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Remote central locking
- Navigation system
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Leather seat trim
- Rear parking sensor
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Dented
2 Or Less UpTo 10mm



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
1 To 5



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		