

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GJ71UAD

Mazda CX-30 2.0 e-Skyactiv X MHEV Sport Lux 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	TBC		
Details					
Reg. date	24/10/2021	VIN	JMZDM6WH600216844	CAP Average	£13,650.00
Year	2021	Body Style	Hatchback	CAP Below	£12,350.00
Mileage	23,589 Miles	Keys	2	Gearbox	MANUAL
	Warranted	MOT Due	23/10/2025	Gears	6
Fuel Type	Petrol	CAP Clean	£15.000.00	Doors	5
Colour	BLUE				

£65 ADDITIONAL FEE.

Tyres			
NSF	BRIDGESTONE	4.0mm	
NSR	BRIDGESTONE	5.0mm	
OSF	BRIDGESTONE	4.0mm	
OSR	BRIDGESTONE	5.0mm	
Spare			

Features

- Bluetooth connection
- Park assist cameraRadio/CD
- Air conditioning
- Rear electric windows
 Drivers airbag
 Central locking
- Front parking sensor Rear parking sensor Body coloured bumpers Climate control Rear headrests December site control

•

- ٠
- Passenger airbag Remote central locking
- · Heated front seat
- Rear wiperElectric door mirrorsFront armrest
- Metallic Paint
- Traction control .
- Cloth seat trim

- Navigation system
 Telephone
 Fixed panoramic glass roof
 Front electric windows
- ABS
- Tyre pressure monitor Alloy wheels

Photos



Eastbourne Car Auctions










Condition Check



Damage Photos





ΟK

No

1: Door nsf Chipped Edge Chip

Interior

Carpet Condition	
Seat Condition	

ΟK OK

Upholstery Condition Odour

Chipped

UpTo 10mm

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		