

# VEHICLE INSPECTION REPORT

**HY21DPF**

## Honda Jazz 1.5 i-MMD Hybrid Crosstar EX 5dr eCVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	30/04/2021	VIN	JHMGR6870MS208208	CAP Average	£15,000.00
Year	2021	Body Style	Hatchback	CAP Below	£13,850.00
Mileage	16,379 Miles Warranted	Keys	2	Gearbox	CVT
Fuel Type	Hybrid Electric	MOT Due	29/04/2026	Gears	1
Colour	BLUE	CAP Clean	£16,200.00	Doors	5

£65 ADDITIONAL FEE.

Tyres		
NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Digital radio
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Chipped  
1 To 5

No Image

6: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image



7: Door nsr  
Scratched  
Over 25mm Not Thru Paint

8: Wheel nsr  
Scratched  
Over 50mm

No Image

No Image

9: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

10: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

12: Wheel osf  
Scratched  
Up To 50mm



13: Door osf  
Scratched  
Over 25mm Not Thru Paint

14: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK