

VEHICLE INSPECTION REPORT

LS11CWW

Audi A1 1.2 TFSI Sport 3dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 csape
		V5	Present		
Details					
Reg. date	30/03/2011	Keys	1	CAP Clean	£2,650.00
Year	2011	Service history	Yes	CAP Average	£2,175.00
Mileage	94,237 Miles Warranted	Service documents	Service Book	CAP Below	£1,700.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	WHITE	Last service date	21/02/2023	Gears	5
VIN	WAUZZZ8X0BB054583	Last service miles	80,127	Doors	3
Body Style	Hatchback	MOT Due	21/02/2026		

£65 ADDITIONAL FEE. LAST SERVICE 21/2/23 @ 80127 MILES (10 SERVICES 3 MAIN DEALER) BOOK

Tyres

NSF	BUDGET	3.0mm	
NSR	CONTINENTAL	3.0mm	
OSF	BUDGET	3.0mm	
OSR	DUNLOP	5.0mm	
Spare			

Features

- Cruise controlRadio/CD
- Front electric windows
- Drivers airbag
- · Remote central locking
- Navigation system
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Electric door mirrors
- Solid Paint
- Traction control
- Leather seat trim
- Telephone
- Air conditioning
- ABS
- Central locking
- Alloy wheels

Photos













Eastbourne Car Auctions










Condition Check



Damage Photos



1: Wheel osf Scratched Over 50mm



2: Door osf Chipped Edge Chip



3: Wheel osr Scratched Over 50mm



4: Bumper Rear Scratched 25 to 100mm Thru Paint



5: Wheel nsr Scratched Over 50mm



6: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



7: Wheel nsf Scratched Over 50mm



8: Bonnet Chipped 1 To 5



9: Screen Front Chipped UpTo 10mm



10: Door nsf Dented Between 10mm + 30mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK	J	
-			
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK