



# VEHICLE INSPECTION REPORT

**FV70LJF**

## Vauxhall Astra 1.2 Turbo 145 SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/10/2020	Body Style	Hatchback	Last service miles	23,620
Year	2020	Keys	2	MOT Due	07/07/2026
Mileage	24,574 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	4	Doors	5
VIN	W0VBF6EW5LG048831	Last service date	12/06/2025		

### £100 ADDITIONAL FEE

Last service 12/06/2025 at 23,620 miles- 4 services (3 main dealer) Book EML light on  
Car has been plugged in and detects Turbo/supercharger underboost

### Tyres

NSF	AVON	5.0mm
NSR	CONTINENTAL	4.0mm
OSF	GT RADIAL	5.0mm
OSR	CONTINENTAL	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint




4: Wing nsf  
Dented  
Over 2 UpTo 10mm

No Image

5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Wheel nsf  
Scratched  
Over 50mm




7: Door nsf  
Chipped  
1 To 5

No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Dented  
2 Or Less UpTo 10mm



10: Door nsr  
Scratched  
Over 25mm Not Thru Paint




11: Qtr Panel nsr  
Chipped  
1 To 5



12: Wheel nsr  
Scratched  
Up To 50mm



13: Bumper Rear  
Chipped  
Multiple Chips




14: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint





15: Boot Lid  
Chipped  
1 To 5




16: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



17: Wheel osr  
Scratched  
Up To 50mm



18: Door osr  
Chipped  
1 To 5



19: Door osr  
Scratched  
Over 25mm Not Thru Paint




20: Door osf  
Chipped  
1 To 5



21: Wing osf  
Chipped  
1 To 5



22: Wheel osf  
Scratched  
Up To 50mm



23: Screen Front  
Chipped  
UpTo 10mm

### Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

## Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK