



VEHICLE INSPECTION REPORT

RV08VLU

Fiat 500 1.2 Sport 3dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date 22/05/2008

Year 2008

Mileage 110,303 Miles
Warranted

Fuel Type Petrol

Colour BLUE

VIN ZFA31200000119973

Body Style Hatchback

Keys 1

Service history None

MOT Due 02/07/2025

CAP Clean £890.00

CAP Average £490.00

CAP Below £200.00

Gearbox MANUAL

Gears 5

Doors 3

£100 ADDITIONAL FEE Eml on

Tyres

NSF BUDGET 4.0mm

NSR BUDGET 4.0mm

OSF BUDGET 3.0mm

OSR BUDGET 4.0mm

Spare

Features


- PAS
- Radio/CD
- Climate control
- Rear electric windows
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- ABS
- Remote central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Bumper Front Moulding
Broken
Replace



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5




7: Door nsf
Chipped
1 To 5

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5




10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Over 50mm

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Door osf
Chipped
1 To 5

No Image



17: Door osf
Scratched
Over 25mm Not Thru Paint

18: Wheel osf
Scratched
Over 50mm

No Image



19: Wing osf
Scratched
Over 25mm Not Thru Paint

20: Seat Base Cover osf
Torn
Over 3mm



21: Door Lock nsf
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK