



## VEHICLE INSPECTION REPORT

**AP68KWT**

### BMW X2 sDrive 20i M Sport X 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



#### Details

Reg. date	28/11/2018	VIN	WBAYH32030EH37724	CAP Average	£13,450.00
Year	2018	Body Style	Hatchback	CAP Below	£12,200.00
Mileage	46,248 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Petrol	MOT Due	10/04/2026	Gears	7
Colour	BLUE	CAP Clean	£14,700.00	Doors	5

£65 ADDITIONAL FEE

#### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Chipped  
Multiple Chips



2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

3: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

No Image

4: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

No Image

5: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image

6: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

7: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



8: Bonnet  
Chipped  
1 To 5





9: Bumper Front  
Chipped  
Multiple Chips

No Image

10: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



11: Wheel osf  
Scratched  
Over 50mm

No Image

12: Wing osf  
Scratched  
Over 25mm Not Thru Paint



13: Door osf  
Chipped  
1 To 5

No Image

14: Door osr  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK