



VEHICLE INSPECTION REPORT

GL62BLJ

Kia Picanto 1.0 1 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 03/01/2013

Year 2013

Mileage 84,658 Miles
Warranted

Fuel Type Petrol

Colour RED

VIN KNABE511LDT424686

Body Style Hatchback

Keys 1

Service history Yes

Service documents Service Book

Number of stamps 10

Last service date 16/08/2022

Last service miles 66,431

MOT Due 01/10/2025

CAP Clean £1,600.00

CAP Average £1,200.00

CAP Below £800.00

Gearbox MANUAL

Gears 5

Doors 5

Last Service: 16/08/2022 at 66431 miles. (10 services (3 main dealer)) Clutch fault

Tyres

NSF FALKEN 4.0mm

NSR FALKEN 4.0mm

OSF FALKEN 4.0mm

OSR FALKEN 4.0mm

Spare

Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Chipped
1 To 5




5: Door nsr
Chipped
1 To 5



6: Qtr Panel nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Boot Lid
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Rusted
Over 5mm




10: Door osr
Poor Previous Repair
Poor Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Wing osf
Chipped
1 To 5



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK