

VEHICLE INSPECTION REPORT

GY18GRF

Citroen C1 1.0 VTi Furio 3dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		grape Grape
		V5	Present		
Details					
Reg. date	19/06/2018	Keys	2	CAP Average	£3,900.00
Year	2018	Service history	Yes	CAP Below	£3,275.00
Mileage	23,611 Miles Warranted	Number of stamps	9	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	16/06/2025	Gears	5
Colour	WHITE	Last service miles	23,533	Doors	3
VIN	VF7PSCFBCHR654260	MOT Due	20/06/2026		
Body Style	Hatchback	CAP Clean	£4,525.00		
Tyres					
NSF	AVON			3.0mm	
NSR	TOYO			3.0mm	
OSF	AVON			3.0mm	
OSR	TOYO			3.0mm	
Spare					

Features

- Rear parking sensor
 Body coloured bumpers
 Solid Paint
 Traction control

- Cloth seat trim
- Rear wiper Air conditioning
- All conditioningABSTyre pressure monitorAlloy wheels

- TelephoneFront electric windowsDrivers airbagCentral locking

- Radio/CD
- Rear headrests
- Passenger airbagRemote central locking

Photos






















Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips



3: Wheel nsf Scratched Up To 50mm



4: Door nsf Chipped 1 To 5

No Image

5: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



6: Wheel nsr Scratched Over 50mm



7: Bumper Rear Chipped Multiple Chips

No Image

8: Qtr Panel osr Scratched Over 25mm Not Thru Paint



9: Door osf Chipped 1 To 5



10: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionOKUpholstery ConditionOKSeat ConditionOKOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated OK		Service indicator light illuminated	
ABS light illuminated OK			
Windows	OK	Radio	OK
		Steering	OK