



# VEHICLE INSPECTION REPORT

**NA62VXJ**

## Skoda Fabia 1.2 TSI 105 SE Plus 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	16/11/2012	Keys	2	CAP Clean	£2,625.00
Year	2012	Service history	Yes	CAP Average	£2,200.00
Mileage	81,248 Miles Warranted	Service documents	Printout	CAP Below	£1,750.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	SEMI AUTO
Colour	YELLOW	Last service date	14/02/2025	Gears	5
VIN	TMBFN25J6D3060619	Last service miles	78,980	Doors	5
Body Style	Hatchback	MOT Due	15/02/2026		

£65 ADDITIONAL FEE. Last Service: 14/02/2025 at 78980 miles. (7 services )

### Tyres

NSF	UNIROYAL	2.0mm
NSR	BUDGET	3.0mm
OSF	UNIROYAL	3.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Poor Previous Repair  
Poor Colour





3: Wing nsf  
Dented  
Over 30mm



4: Wheel nsf  
Scratched  
Over 50mm



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsf  
Poor Previous Repair  
Poor Colour



7: Door nsr  
Poor Previous Repair  
Poor Paint




8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint




11: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



12: Wheel osr  
Scratched  
Up To 50mm



13: Qtr Panel osr  
Chipped  
Multiple Chips



14: Door osr  
Scratched  
Over 25mm Thru Paint





15: Door osf  
Scratched  
Over 25mm Thru Paint



16: Wing osf  
Dented  
Between 10mm + 30mm



17: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK