



VEHICLE INSPECTION REPORT

EJ65RZV

Renault Captur 0.9 TCE 90 Signature Nav 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
3

Details

Reg. date	30/11/2015	VIN	VF12RE11A54233974	CAP Average	£4,800.00
Year	2015	Body Style	Hatchback	CAP Below	£4,075.00
Mileage	30,294 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	22/07/2025	Gears	5
Colour	GREY/BLACK	CAP Clean	£5,525.00	Doors	5

£65 ADDITIONAL FEE.


Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Heated front seat
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Boot Lid
Dented
Over 30mm



11: Bumper Rear
Chipped
Multiple Chips



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osr
Dented
Over 2 UpTo 10mm



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Wheel of front
Scratched
Over 50mm



16: Wheel of rear
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK