



VEHICLE INSPECTION REPORT

GD17EES

Skoda Kodiaq 2.0 TDI Edition 4x4 5dr DSG [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2017	Keys	2	CAP Clean	£11,850.00
Year	2017	Service history	Yes	CAP Average	£10,650.00
Mileage	99,047 Miles Warranted	Service documents	Printout	CAP Below	£9,425.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	SEMI AUTO
Colour	WHITE	Last service date	07/02/2025	Gears	7
VIN	TMBMJ7NS7H8025539	Last service miles	92,900		
Body Style	Estate	MOT Due	Expired		

LAST SERVICE 07-02-2025 @92900 MILES (9 SERVICES) Eml light is on , gearbox emergency mode displayed warning light

Tyres

NSF	RADAR	5.0mm
NSR	PIRELLI	5.0mm
OSF	TRIANGLE	3.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Park assist camera
- Digital radio
- Space saver spare wheel
- Electrically adjustable passenger seat
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Body coloured bumpers
- Towbar
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5



3: Door nsf
Poor Previous Repair
Poor Paint



4: Door nsr
Dented
Between 10mm + 30mm



5: Bumper Rear
Dented
With Paint Damage



6: Door osr
Dented
Between 10mm + 30mm



7: Door osf
Dented
With Paint Damage



8: Screen Front
Chipped
Over 10mm



9: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK