



VEHICLE INSPECTION REPORT

PF13KWG

Citroen C3 Picasso 1.6 VTi 16V VTR+ 5dr EGS6

Inspection

Serious Damage? No

Vehicle

VAT Margin
V5 Buyer To Apply

nama
GRADE
5

Details

Reg. date	31/07/2013	VIN	VF7SH5FS8DT539929	CAP Below	£950.00
Year	2013	Body Style	MPV	Gearbox	SEMI AUTO
Mileage	100,318 Miles Warranted	MOT Due	22/02/2026	Gears	6
Fuel Type	Petrol	CAP Clean	£1,800.00		
Colour	SILVER	CAP Average	£1,375.00		

£100 ADDITIONAL FEE.

NO V5

NO SERVICE HISTORY

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: Door nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Sill ns
Dented
Over 30% Of Panel



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Lamp nsr
Broken
Replace



12: Qtr Panel nsr
Dented
Between 10mm + 30mm



13: Door osf
Dented
Over 30mm



14: Wing osf
Dented
Between 10mm + 30mm



15: Wheel osf
Scratched
Over 50mm



16: Seat Back Cover osr
Torn
Over 3mm



17: Headrest Assy Rear Seat ns
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK