

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX19YCY

Nissan Micra 1.0 IG 71 Acenta Limited Edition 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grade
		V5	Present		
Details					
Reg. date	15/03/2019	Keys	2	CAP Clean	£6,900.00
Year	2019	Service history	Yes	CAP Average	£6,000.00
Mileage	22,508 Miles Warranted	Service documents	Service Book	CAP Below	£5,125.00
		Number of stamps	5	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	27/08/2024	Gears	5
Colour	BLACK	Last service miles	18,332	Doors	5
VIN	VNVK1400261209878	MOT Due	29/08/2025		-
Body Style	Hatchback		20,00,2020		

Last Service - 27.08.2024 at 18332 miles (5 main dealer services) Eml light is on

Cruise control

Passenger airbag

· Cloth seat trim

Air conditioning Height adjustable drivers seat 3x3 point rear seat belts

٠

٠

٠

Tyres			
NSF	TRIANGLE	3.0mm	
NSR	TRIANGLE	5.0mm	
OSF	TRIANGLE	3.0mm	
OSR	BUDGET	6.0mm	
Spare			

Features

Bluetooth connection

- Steering wheel mounted controls
 Front fog lights
 Front fog lights
- Front head restraints
- Solid Paint
- Isofix child seat anchor points Central locking

- PAS
 - Body coloured bumpers
 Folding rear seats
 Rear electric windows

 - ABS ٠
 - Side airbags
 Alloy wheels

- Rear wiper Electric door mirrors
- Front electric windows
 Rear headrests
- Drivers airbag
 Traction control

Photos





















Condition Check



Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Bonnet Chipped Multiple Chips



3: Wheel nsf Scratched Over 50mm



5: Door nsf Dented With Paint Damage



4: Wing nsf Scratched Over 25mm Thru Paint



6: Door nsr Scratched UpTo 25mm Thru Paint



7: Qtr Panel nsr Scratched Over 25mm Thru Paint



8: Bumper Rear Scratched Over 100mm Thru Paint







11: Wheel osf Scratched Over 50mm

Interior

Carpet Condition Seat Condition

Average Average Upholstery Condition Odour

Chipped

1 To 5

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	Parking Brake OK Gearbox		OK
		No Excessive Smoking	OK



10: Door osf Chipped Edge Chip



EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK