



VEHICLE INSPECTION REPORT

LD65MWN

Vauxhall Adam 1.2i Slam 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	27/11/2015	Keys	2	CAP Clean	£2,025.00
Year	2015	Service history	Yes	CAP Average	£1,600.00
Mileage	113,101 Miles Warranted	Service documents	Service Book	CAP Below	£1,150.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	WHITE	Last service date	04/03/2022	Gears	5
VIN	W0LOMAP08E6112278	Last service miles	67,924	Doors	3
Body Style	Hatchback	MOT Due	06/03/2026		

Last Service - 04.03.2022 at 67924 miles (6 services)
 Gear linkage fault

Tyres

NSF	BUDGET	3.0mm
NSR	LAUFENN	4.0mm
OSF	BUDGET	2.0mm
OSR	LAUFENN	3.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Over 30% Of Panel



5: Door nsf
Dented
Over 30mm



6: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image



10: Qtr Panel osr
Dented
Between 10mm + 30mm

9: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osf
Dented
Over 2 UpTo 10mm

No Image

13: Door osf
Scratched
Over 25mm Not Thru Paint

No Image

14: Wing osf
Scratched
Over 25mm Not Thru Paint



15: Wheel osf
 Scratched
 Over 50mm

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK