



VEHICLE INSPECTION REPORT

NX13YYB

Audi A1 1.6 TDI Sport 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	28/03/2013	Keys	2	CAP Clean	£2,700.00
Year	2013	Service history	Yes	CAP Average	£2,225.00
Mileage	92,859 Miles Warranted	Service documents	Printout	CAP Below	£1,750.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	MANUAL
Colour	BLACK	Last service date	27/09/2023	Gears	5
VIN	WAUZZZ8X5DB089350	Last service miles	85,540	Doors	3
Body Style	Hatchback	MOT Due	23/04/2026		

Last service 27/09/2023 at 85540 miles, 7 services (2 main dealer services)

Tyres

NSF	FALKEN	6.0mm
NSR	FALKEN	6.0mm
OSF	FALKEN	6.0mm
OSR	DAVANTI	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Leather seat trim
- Telephone
- Air conditioning
- ABS
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wheel nsr
Scratched
Up To 50mm



3: Wheel nsf
Scratched
Over 50mm



4: Bumper Front
Poor Previous Repair
Poor Paint



5: Bonnet
Chipped
Multiple Chips



6: Wing nsf
Poor Previous Repair
Poor Paint



7: Door nsf
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Poor Previous Repair
Poor Paint

No Image



10: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Door osf
Chipped
1 To 5



13: Wing osf
Scratched
Over 25mm Thru Paint



14: Screen Front
Chipped
UpTo 10mm



15: Boot Lid
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK