

# VEHICLE INSPECTION REPORT

**EO600DP**

## Ford Fusion 1.6 Titanium 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

nama  
GRADE  
**3**

### Details

|            |                        |                    |              |             |           |
|------------|------------------------|--------------------|--------------|-------------|-----------|
| Reg. date  | 20/09/2010             | Keys               | 2            | CAP Clean   | £1,400.00 |
| Year       | 2010                   | Service history    | Yes          | CAP Average | £1,000.00 |
| Mileage    | 78,178 Miles Warranted | Service documents  | Service Book | CAP Below   | £575.00   |
| Fuel Type  | Petrol                 | Number of stamps   | 9            | Gearbox     | MANUAL    |
| Colour     | Silver                 | Last service date  | 26/06/2019   | Doors       | 5         |
| VIN        | WF0UXXGAJUAB49996      | Last service miles | 54,607       |             |           |
| Body Style | Hatchback              | MOT Due            | 25/12/2025   |             |           |

Last Service - 26.06.2019 at 54607 miles (9 services)

### Tyres

|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 5.0mm |
| NSR   | BUDGET | 6.0mm |
| OSF   | BUDGET | 6.0mm |
| OSR   | BUDGET | 6.0mm |
| Spare | BUDGET | OK    |

## Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Passenger airbag
- Leather seat trim
- PAS
- Radio/CD
- Front armrest
- ABS
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- ESP
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
1 To 5





3: Door Moulding osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



4: Door osr  
Dented  
Between 10mm + 30mm




5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Tailgate  
Dented  
With Paint Damage



7: Wheel osr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Dented  
Between 10mm + 30mm



10: Door Moulding nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint



12: Bonnet  
Chipped  
1 To 5



13: Wheel nsr  
Scratched  
Over 50mm



14: Wheel nsf  
Scratched  
Over 50mm





15: Seat Base Cover nsf  
 Holed  
 UpTo 3mm

Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

|                          |    |  |    |
|--------------------------|----|--|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |  |    |
| Windows                  | OK | Radio  | OK |
|                          |    | Steering                                       | OK |