



VEHICLE INSPECTION REPORT

LM21MMK

Jeep Renegade 1.0 T3 GSE Limited 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2021	Keys	2	CAP Clean	£11,150.00
Year	2021	Service history	Yes	CAP Average	£9,975.00
Mileage	34,125 Miles Warranted	Service documents	Service Book	CAP Below	£8,800.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	BLACK	Last service date	26/07/2022	Gears	6
VIN	1C4NJCD33MPM64227	Last service miles	14,627		
Body Style	Estate	MOT Due	03/04/2026		

£65 ADDITIONAL FEE LAST SERVICE 26/7/22 @ 14627 MILES (1 SERVICE) BOOK

Tyres

NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	3.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Tailgate
Dented
With Paint Damage




9: Qtr Panel osr
Dented
With Paint Damage



10: Door osr
Chipped
1 To 5



11: Wing osf
Scratched
UpTo 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK