

## **VEHICLE INSPECTION REPORT**

**MK17YLC** 

### Kia Picanto 1.0 65 1 Air 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grade.
		V5	Buyer To Apply	_	
Details					
Reg. date	06/03/2017	Keys	2	CAP Clean	£3,125.00
Year	2017	Service history	Yes	CAP Average	£2,600.00
Mileage	74,882 Miles Warranted	Service documents	Service Book	CAP Below	£2,100.00
		Number of stamps	6	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	30/05/2024	Gears	5
Colour	SILVER	Last service miles	67,218	Doors	 5
VIN	KNABE511LHT433849	MOT Due	13/05/2026		
Body Style	Hatchback		. 0, 00, 2020	<u> </u>	

#### £100 ADDITIONAL FEE. Last service 30/5/24 at 67,218 miles, 6 services (0 main dealer services)

Tyres			
NSF	BUDGET	5.0mm	
NSR	BUDGET	5.0mm	
OSF	BUDGET	5.0mm	
OSR	HANKOOK	4.0mm	
Spare			

#### **Features**

- Bluetooth connection
- Radio/CD
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Front head restraints
- 3x3 point rear seat belts
  Passenger airbag
  Cloth seat trim
- Rear wiper
- Rear wiper
  Air conditioning
  Height adjustable drivers seat
  ABS
  Side airbags
  Steel wheels

- Steering wheel mounted controls
  Folding rear seats
  Rear headrests
  Drivers airbag
  Central locking

#### **Photos**












## **Condition Check**



## **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched 25 to 100mm Thru Paint

# No Image

# No Image

3: Door nsf Scratched Over 25mm Not Thru Paint



5: Bumper Rear Scratched 25 to 100mm Thru Paint



6: Qtr Panel osr Scratched Over 25mm Thru Paint

4: Wing nsf

Scratched



7: Door osr Chipped Edge Chip



8: Door osf Chipped Edge Chip



9: Door Mirror Assy osf Broken Replace



10: Wing osf Chipped 1 To 5

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake OK		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK