



VEHICLE INSPECTION REPORT

WV62EHJ

Vauxhall Corsa 1.2 Exclusiv 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/09/2012	Service history	Yes	CAP Average	£880.00
Year	2012	Service documents	Printout	CAP Below	£475.00
Mileage	92,784 Miles Warranted	Number of stamps	1	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	28/05/2025	Gears	5
Colour	BLACK	Last service miles	92,305	Doors	5
VIN	W0L0SDL68C4189860	MOT Due	22/06/2026		
Body Style	Hatchback	CAP Clean	£1,275.00		

LAST SERVICE 28/5/25 @ 92305 MILES (1 SERVICE) PRINT

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Full size spare wheel
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Steel wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsf
Dented
Between 10mm + 30mm



4: Door nsr
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage




6: Tailgate
Dented
Over 30mm



7: Bumper Rear
Dented
With Paint Damage



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door nsf
Dented
Over 30mm



10: Wing osf
Scratched
UpTo 25mm Thru Paint



11: Carpets Front
Holed
Over 3mm



12: Bumper Rear
Insecure
Action Required

Interior

Carpet Condition Poor
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK