



# VEHICLE INSPECTION REPORT

**GX64OPR**

## Vauxhall Antara 2.2 CDTi SE Nav 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
2

### Details

Reg. date	01/09/2014	Body Style	Hatchback	CAP Below	£1,200.00
Year	2014	Keys	2	Gearbox	MANUAL
Mileage	54,201 Miles Warranted	Service history	None	Gears	6
Fuel Type	Diesel	MOT Due	21/11/2025	Doors	5
Colour	WHITE	CAP Clean	£1,975.00		
VIN	W0LLJ6EHXFB000272	CAP Average	£1,575.00		

No Service History EML LIGHT ON

Tyres		
NSF	MICHELIN	2.0mm
NSR	PETLAS	6.0mm
OSF	MICHELIN	5.0mm
OSR	BUDGET	1.7mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: A Post os  
Chipped  
1 To 5





3: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Not Thru Paint



4: Door osr  
Scratched  
UpTo 25mm Not Thru Paint



5: Wheel osr  
Scratched  
Over 50mm



6: Door osf  
Dented  
2 Or Less UpTo 10mm



7: Tailgate  
Scratched  
Over 25mm Not Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Door nsf  
Chipped  
1 To 5



10: Wheel nsf  
Scratched  
Over 50mm



11: Bumper Front  
Chipped  
Multiple Chips



12: Bonnet  
Chipped  
1 To 5



13: Tailgate  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK