

VEHICLE INSPECTION REPORT

AP07TZY

Toyota Auris 2.0 D-4D TR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	31/03/2007	VIN	JTNKD56E901004549	CAP Below	£200.00
Year	2007	Body Style	Hatchback	Gearbox	MANUAL
Mileage	84,179 Miles Not Warranted	Keys	2	Doors	5
Fuel Type	Diesel	CAP Clean	£920.00		
Colour	Grey	CAP Average	£520.00		

Vibration at idle


Tyres

NSF	FALKEN	3.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Audio remote control
- Air conditioning
- Rear armrest
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing osf
Chipped
1 To 5



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Scratched
Over 25mm Not Thru Paint



6: Door osr
Chipped
Multiple Chips



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



9: Bumper Rear
Poor Previous Repair
Rippled Over 30%



10: Boot Lid
Chipped
1 To 5



11: Qtr Panel nsr
Chipped
1 To 5




12: Wheel nsr
Scratched
Over 50mm



13: Door nsr
Chipped
1 To 5



14: Door nsf
Chipped
Multiple Chips



15: Wheel nsf
Scratched
Over 50mm

16: Wing nsf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK