



# VEHICLE INSPECTION REPORT

**GY66HVT**

## Citroen C3 1.2 PureTech 82 Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/12/2016	Keys	2	CAP Clean	£1,825.00
Year	2016	Service history	Yes	CAP Average	£1,425.00
Mileage	80,236 Miles Warranted	Service documents	Service Book	CAP Below	£1,025.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	BLACK	Last service date	06/07/2022	Gears	5
VIN	VF7SCHMZ6GW654289	Last service miles	64,825	Doors	5
Body Style	Hatchback	MOT Due	01/12/2025		

Last Service - 06.07.2022 at 64825 miles (6 services) Engine misfire

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Cruise control
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Up To 50mm



2: Wing osf  
Chipped  
1 To 5





3: Door osf  
Dented  
2 Or Less UpTo 10mm



4: Door osf  
Chipped  
Edge Chip



5: Door osr  
Dented  
2 Or Less UpTo 10mm



6: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint





9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Door nsf  
Scratched  
Over 25mm Not Thru Paint



11: Wing nsf  
Dented  
Over 30mm




12: Bumper Front  
Scratched  
UpTo 25mm Thru Paint



13: Bonnet  
Chipped  
1 To 5



14: Roof  
Chipped  
1 To 5



15: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK