

VEHICLE INSPECTION REPORT

GF64MLL

Ford Focus 1.6 Zetec 5dr

Serious Damage? No		venicie	venicie		nama
		VAT	Margin		GRADE CRADE
		V5	Present		
Details					
Reg. date	29/10/2014	Body Style	Hatchback	CAP Below	£725.00
Year	2014	Keys	1	Gearbox	MANUAL
Mileage	135,579 Miles Warranted	Service history	None	Gears	5
		MOT Due	01/11/2025	Doors	5
Fuel Type	Petrol	CAP Clean	£1,525.00		
Colour	WHITE	CAP Average	£1,125.00		
VIN	WF0KXXGCBKEB67	•	,		

£100 ADDITIONAL FEE. NO SERVICE HISTORY Oil leak

Tyres

NSF	NEXEN	5.0mm	
NSR	MICHELIN	5.0mm	
OSF	BUDGET	4.0mm	
OSR	MICHELIN	5.0mm	
Spare			

Features

- Bluetooth connection
- Radio/CD
- Air conditioningHeight adjustable drivers seatABS
- Side airbags
- · Alloy wheels

- PAS
- · Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- · Rear wiper
- · Electric door mirrors
- Front electric windows
- Solid Paint
- ESP
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos










Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Scratched Over 25mm Thru Paint



5: Door nsf Chipped Edge Chip



6: Aperture Seal nsr Broken Replace



7: Wheel nsr Scratched Over 50mm



8: Door nsr Chipped 1 To 5

No Image

9: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



11: Tailgate Rusted Over 5mm



13: Door osf Chipped Edge Chip



10: Bumper Rear Scratched Over 100mm Thru Paint



12: Door osr Chipped Edge Chip



14: Wheel osf Scratched Over 50mm



15: Switches And Controls Broken Replace



16: Other N/A N/A



17: Seat Back Cover osf Scuffed UpTo 25mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
		Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK