



VEHICLE INSPECTION REPORT

GU67VUH

Audi Q5 2.0 TDI Quattro Sport 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2017	Keys	2	CAP Clean	£12,150.00
Year	2017	Service history	Yes	CAP Average	£10,950.00
Mileage	98,932 Miles Warranted	Service documents	Printout	CAP Below	£9,750.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	16/10/2024	Gears	7
VIN	WAUZZZFY8H2045960	Last service miles	91,937		
Body Style	Estate	MOT Due	21/10/2025		

£65 ADDITIONAL FEE. Last service 16/10/2024 at 91,937 miles, 8 services (6 MAIN DEALER SERVICES) Eml on

Tyres



NSF	GENERAL TIRE	Illegal
NSR	BUDGET	4.0mm
OSF	GENERAL TIRE	2.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
 - PAS
 - Audio remote control
 - Air conditioning
 - Front head restraints
 - Rear headrests
 - Drivers airbag
 - Side airbags
 - Leather seat trim
- Cruise control
 - Rear parking sensor
 - Digital radio
 - Climate control
 - Height adjustable drivers seat
 - Solid Paint
 - ESP
 - Traction control
 - Alloy wheels
- Front parking sensor
 - Rear wiper
 - Body coloured bumpers
 - Front armrest
 - Rear armrest
 - 3x3 point rear seat belts
 - Isofix child seat anchor points
 - Central locking
- Navigation system
 - Steering wheel mounted controls
 - Electric door mirrors
 - Front electric windows
 - Rear electric windows
 - ABS
 - Passenger airbag
 - Remote central locking

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
 Scratched
 Up To 50mm



4: Wing nsf
 Chipped
 1 To 5




5: Door nsf
 Dented
 Between 10mm + 30mm



6: Door nsf
 Scratched
 Over 25mm Not Thru Paint



7: Door nsr
 Chipped
 1 To 5



8: Door nsr
 Scratched
 Over 25mm Not Thru Paint

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Up To 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

13: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image


14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Dented
Over 2 UpTo 10mm



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wing osf
Dented
Over 2 UpTo 10mm



19: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK