

VEHICLE INSPECTION REPORT



Dacia Sandero 1.0 SCe Ambiance 5dr

Inspection		Vehicle			nama "
Serious Damage?	No	VAT	Margin		GRADE.
		V5	Present		
Details					
Reg. date	14/03/2018	Keys	2	CAP Clean	£2,175.00
Year	2018	Service history	Yes	CAP Average	£1,725.00
Mileage	86,514 Miles Warranted	Service documents	Printout	CAP Below	£1,275.00
		Number of stamps	1	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	28/10/2024	Gears	5
Colour	WHITE	Last service miles	77,390	Doors	5
VIN	UU15SDMC560017079	MOT Due	13/03/2026		
Body Style	Hatchback				

£65 ADDITIONAL FEE. Last service 28/10/2024 at 77,390 miles 1 service (0 main dealer) Eml light is on

Tyres			
NSF	AVON	3.0mm	
NSR	KUMHO	5.0mm	
OSF	AVON	3.0mm	
OSR	KUMHO	5.0mm	
Spare			

Features

- Bluetooth connection
- Body coloured bumpers
 Front head restraints
- ABSSide airbags
- Steel wheels
- PAS
- Air conditioning
- Rear headrests Drivers airbag Central locking

- Rear wiperFolding rear seatsSolid Paint
- ESP
- Remote central locking
- Audio remote control
- Front electric windows
- 3x3 point rear seat belts
- Rear airbags Cloth seat trim

Photos










Condition Check




Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Dented With Paint Damage



3: Wing nsf Scratched UpTo 25mm Thru Paint



4: Sill ns Dented Over 30mm



5: Door nsf Scratched UpTo 25mm Thru Paint



6: Bumper Rear Scratched Over 100mm Thru Paint



7: Door osr Chipped Edge Chip



8: Door osf Chipped Edge Chip



9: Wing osf Chipped 1 To 5



10: Screen Front Chipped UpTo 10mm



11: Roof Chipped Edge Chip

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OI	Gearbox 1st and Reverse Test	OK
Brakes OI	Clutch Slip Test from Static	OK
Parking Brake OI	Gearbox Static Gear Selection (engine running)	OK
	No Excessive Smoking	OK

EML light illuminated Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK