



VEHICLE INSPECTION REPORT

RO59BYX

Kia Rio 1.4 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	22/10/2009	Keys	2	CAP Average	£280.00
Year	2009	Service history	Yes	CAP Below	£200.00
Mileage	94,776 Miles Warranted	Number of stamps	6	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	09/08/2024	Gears	5
Colour	SILVER	Last service miles	92,364	Doors	5
VIN	KNADE241296593092	MOT Due	Expired		
Body Style	Hatchback	CAP Clean	£650.00		

£100 ADDITIONAL FEE
EXPIRED MOT.

Last service 09/08/2024 at 92,364 miles, 6 services confirmed by LISS GARAGE SERVICES

Tyres		
NSF	FALKEN	5.0mm
NSR	KUMHO	5.0mm
OSF	FALKEN	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- PAS
 - Front fog lights
 - Front head restraints
 - 3x3 point rear seat belts
 - Passenger airbag
- Rear wiper
 - Air conditioning
 - Height adjustable drivers seat
 - ABS
 - Central locking
- Media storage
 - Folding rear seats
 - Rear headrests
 - Drivers airbag
 - Cloth seat trim
- Body coloured bumpers
 - Front electric windows
 - Metallic Paint
 - Isofix child seat anchor points
 - Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Headlamp nsf
Broken
Replace



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
Over 30mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osr
Dented
With Paint Damage



12: Door Moulding osr
Scuffed (Unpainted)
Over 100mm



13: Door osf
Dented
Over 30mm



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK