



# VEHICLE INSPECTION REPORT

**FG13YWR**

## Volkswagen Golf 2.0 TDI BlueMotion Tech SE 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	24/05/2013	Keys	2	CAP Clean	£2,050.00
Year	2013	Service history	Yes	CAP Average	£1,625.00
Mileage	151,991 Miles Warranted	Service documents	Service Book	CAP Below	£1,200.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	MANUAL
Colour	WHITE	Last service date	03/11/2017	Gears	6
VIN	WVWZZZ1KZDK013258	Last service miles	56,119		
Body Style	Convertible	MOT Due	28/11/2025		

Last Service - 03.11.2017 at 56119 miles (6 main dealer services) Rear window buttons missing

### Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Electric door mirrors
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Electric sunroof
- Front electric windows
- ABS
- Central locking

## Photos





Condition Check



9  
Damage Photos



1: Other  
N/A  
N/A



2: Bonnet  
Chipped  
1 To 5





3: Wheel osf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Between 10mm + 30mm



5: Qtr Panel nsr  
Dented  
Over 30mm



6: Wheel nsr  
Scratched  
Over 50mm



7: Wheel osr  
Scratched  
Over 50mm



8: Qtr Panel osr  
Rusted  
Over 5mm



9: Door osf  
Dented  
With Paint Damage



10: Bumper Front  
Scratched  
25 to 100mm Thru Paint



11: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK