



VEHICLE INSPECTION REPORT

RE13WUU

Renault Clio 0.9 TCE 90 Dynamique MediaNav Energy 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/06/2013	Keys	2	CAP Clean	£2,575.00
Year	2013	Service history	Yes	CAP Average	£2,100.00
Mileage	66,723 Miles Warranted	Service documents	Service Book	CAP Below	£1,675.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	GREY	Last service date	28/12/2022	Gears	5
VIN	VF15R5A0H49025787	Last service miles	52,134	Doors	5
Body Style	Hatchback	MOT Due	03/01/2026		

LAST SERVICE 28/12/22 @ 52134 MILES (9 SERVICES 7 MAIN DEALER) BOOK

Tyres


NSF	CONTINENTAL	6.0mm
NSR	CONTINENTAL	6.0mm
OSF	KUMHO	5.0mm
OSR	CONTINENTAL	6.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wheel nsf
Scratched
Over 50mm



2: Bonnet
Scratched
Over 25mm Not Thru Paint



3: Door nsf
Chipped
Edge Chip



4: Qtr Panel nsr
Dented
With Paint Damage



5: Wheel nsr
Scratched
Over 50mm



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel osr
Dented
Over 30mm



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door osf
Scratched
Over 25mm Thru Paint



10: Wheel osf
Scratched
Over 50mm



11: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK