



VEHICLE INSPECTION REPORT

GK11ZRJ

Skoda Fabia 1.6 TDI CR 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
2

Details

Reg. date	25/03/2011	VIN	TMBKL25J8B3151781	CAP Below	£350.00
Year	2011	Body Style	Estate	Gearbox	MANUAL
Mileage	118,744 Miles Warranted	Keys	2	Doors	5
Fuel Type	Diesel	CAP Clean	£1,125.00		
Colour	Beige	CAP Average	£720.00		

£65 ADDITIONAL FEE EML LIGHT ON

Tyres

NSF	MAZZINI	5.0mm
NSR	MAZZINI	2.2mm
OSF	MAZZINI	4.0mm
OSR	MAZZINI	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- ESP
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Door osf
Chipped
1 To 5



3: Bumper Rear
Scratched
Up To 25mm Thru Paint



4: Bumper Rear
Chipped
1 To 5



5: Door nsr
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Bumper Front
Chipped
1 To 5



8: Bonnet
Chipped
1 To 5



9: Wheel osf
Scratched
Over 50mm



10: Wheel osr
Scratched
Up To 50mm



11: Wheel nsr
Scratched
Over 50mm



12: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK