



VEHICLE INSPECTION REPORT

FL14FLC

Fiat Doblo 1.3 Multijet 16V Van Start Stop

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present



Details

Reg. date	21/03/2014	Keys	3	CAP Clean	£1,425.00
Year	2014	Service history	Yes	CAP Average	£1,150.00
Mileage	100,874 Miles Warranted	Service documents	Printout	CAP Below	£800.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	MANUAL
Colour	WHITE	Last service date	17/06/2025	Gears	5
VIN	ZFA26300006144179	Last service miles	99,370	Doors	6
Body Style	Panel Van	MOT Due	22/06/2026		

£100 ADDITIONAL FEE.

Last service 17/06/2025 at 99,370 miles- 7 services (0 main dealer)

Tyres

NSF	RIKEN	5.0mm
NSR	SAILUN	5.0mm
OSF	RIKEN	5.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Bluetooth connection
- Front electric windows
- Central locking
- Rear parking sensor
- Metallic Paint
- Cloth seat trim
- Radio/CD
- Drivers airbag
- Air conditioning
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
Over 30mm



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
Over 30mm



7: Tailgate
Scratched
Over 25mm Thru Paint



8: Roof
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage



10: Door osr
Dented
Over 30mm



11: Door osf
Dented
Over 30mm



12: Wing osf
Dented
With Paint Damage



13: Flasher Side Repeater os
Broken
Replace



14: Carpets Front
Holed
Over 3mm



15: Fascia Panel
Broken
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK